

Certification Steps

In order to install FreePower, fabricators must go through the FreePower certification process.

Now certifying preferred fabricators*

01 Approved to be a Certified Fabricator

Approvals can only come from FreePower or a FreePower distributor.

02 Join a fabricator onboarding webinar

Webinars must be scheduled with the representative that approved the fabricator.

03 Receive welcome kit

Welcome kits will be provided, they include: routing bit, drawings, DXF programming file, test report, and more.

04 Complete fabrication testing

Fabricator must complete 5 test cuts to the drawing specs, adhere a bracket to 1 sample, and fill out the test report.

05 Setup showroom & order product

Fabricator purchases a showroom display, receives marketing materials, and applies compatibility labels on quartz.

06 Schedule first install

To ensure your first project goes smooth, fabricator must schedule the first install so FreePower can be available to support.



